

American Mold Lab	Mold Analysis Report American Mold Lab 111 Center Park Drive Suite 125 Knoxville, TN 37922 admin@americanmoldlab.com
--------------------------	--

Client Information
Fiona Westby 10115 NE 62nd Street, # 400 Kirkland, WA 98033 206-920-4001 FionaWestby@yahoo.com

Referred By
NONE

Testing Information
Date Received: 08-07-2015 Date Tested: 08-10-215 Analyzed By: Lab Technician Testing Medium: SDA Temperature: 25 °C

RESULTS
<p>Please note that TNTC indicates the mold colonies were Too Numerous To Count.</p> <p style="text-align: center;">With the methods and materials used, this scale applies to:</p> <p>In House:</p> <ul style="list-style-type: none"> 1 to 4 total colonies per room is within a normal range 5 to 8 colonies per room is a cause for concern (illness possible) 9 total colonies per room is hazardous (illness likely) <p>In Crawl Space:</p> <ul style="list-style-type: none"> Normal range depends on geographical region and crawl space design

Living Room # 2 Bryces	
Mold	Colonies
Alternaria sp	9
Aspergillus sp	4
Aureobasidium sp	21
Penicillium sp	6
Total for the Room: 40	

Bedroom # 2 Bryces bedroom	

Mold	Colonies
Alternaria sp	11
Aspergillus sp	4
Aureobasidium sp	16
Penicillium sp	10
Total for the Room: 41	

Basement Bryces	
Mold	Colonies
Aspergillus sp	9
Candida sp	1
Microsporium sp	16
Penicillium sp	10
Total for the Room: 36	

Lower Storage Fiona's garage storage	
Mold	Colonies
Aspergillus sp	8
Penicillium sp	35
Total for the Room: 43	

Living Room Fiona	
Mold	Colonies
Alternaria sp	2
Aspergillus sp	1
Microsporium sp	38
Total for the Room: 41	

Hall fiona	
Mold	Colonies
Paecilomyces sp	57
Total for the Room: 57	



QUALIFICATIONS TO THIS REPORT:

This report is based on the review of the plates submitted by the customer to the laboratory, and is therefore qualified to the extent that neither American Mold Lab, nor any of its affiliates, performed the collection procedures using the plates. Further this report should not be viewed as an analysis or comprehensive identification of all hazards that may or may not exist within the structure in which the plates were placed, and neither American Mold Lab, nor any of its affiliates make any representation concerning the condition of the structure or environment therein. This report is limited to the identification of the substances noted above that were found on the plates when tested in the laboratory. This report is merely one source of information that may be useful in determining a course of action to take for the possible treatment of the structure, and accordingly, this report should not be used for any other purpose.